

<b>Reference</b>	SSM73662
<b>Models</b>	Discovery Sport / L550
<b>Title</b>	L550 Discovery Sport Front Door weatherstrips
<b>Category</b>	Body
<b>Last modified</b>	22-Jun-2018 00:00:00
<b>Symptom</b>	110000 Sealing
<b>Content</b>	<p><u>Issue:</u> Front door belt Weatherstrips are being replaced. Causal part numbers are:</p> <ul style="list-style-type: none"><li>• LR058620</li><li>• LR058621</li></ul> <p><u>Cause:</u> Customer reports of poor fit and/or deformation of the moulding.</p> <p><u>Action:</u> Please raise an EPQR and attach pictures showing the fit of the weatherstrip against the body and/or any moulding issues to help with further investigations.</p> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>