

Reference	SSM72937
Models	Range Rover Evoque / L538
Title	L538c Range Rover Evoque Convertible Folding Top (Roof) reporting not locked
Category	Body
Last modified	22-Jun-2018 00:00:00
Symptom	105000 Roof Options
Content	<p><u>Issue:</u> Customers are reporting that the folding Convertible Top (Roof) is not operating. They may also report an error message "Top is not locked, less than 50km/h drive".</p> <p>This error has been observed during static position and whilst moving.</p> <p><u>Cause:</u> The folding Top (Roof) action is inhibited.</p> <p><u>Action:</u> The TOPIx workshop manual has now been updated with an initialization procedure to help resolve this issue. The following procedure re-calibrates the rear window operation.</p> <p>Please refer to:</p> <ul style="list-style-type: none"> • TOPIx Workshop manual • 501-18: Folding Top - Folding Top • General Procedures • Folding Top - Initialization <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>