

<b>Reference</b>	SSM73369
<b>Models</b>	Discovery Sport / L550 Range Rover Evoque / L538
<b>Title</b>	Exterior Rear View Mirror - Temperature sensor
<b>Category</b>	Body
<b>Last modified</b>	22-Jun-2018 00:00:00
<b>Symptom</b>	103000 Mirrors
<b>Content</b>	<p><u>Issue:</u> Exterior rear view mirrors are being replaced unnecessarily.</p> <p><u>Cause:</u> Inaccurate temperature readings are being displayed within the vehicle and this is being associated with the external temperature sensor within the exterior rear view mirror housing.</p> <p><u>Action:</u> Retailers should review the diagnosis and testing instructions within the Work Shop Manual first. This can be found under:</p> <ul style="list-style-type: none"> <li>• 5: Body and Paint</li> <li>• 501: Body and Paint</li> <li>• 501-09: Rear View Mirrors</li> <li>• Diagnosis and Testing</li> <li>• Rear View Mirrors</li> </ul> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>