

Reference	SSM72456
Models	Discovery Sport / L550 LR3 / L319 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L494
Title	Range Rover / Sport & Discovery 4 / LR4/ Sport & Evoque Powerfold Door Mirror will not fold
Category	Body
Last modified	28-Jun-2018 00:00:00
Symptom	103000 Mirrors
Attachments	11Door Mirror Loose.mp4

ContentIssue:

Customers may report that the Powerfold Door Mirrors will not Powerfold or are loose -See attached movie file which demonstrates the issue.

Cause:

Customers or external influences such as Car Washes may inadvertently knock the Door Mirror head into the folded position, this will then cause the Mirror head to be loose.

Action:

Please refer to the workshop manual 5. Body and Paint / 501.09 Door Mirror diagnosis and testing, for the reset procedure.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.