



Technical Service Bulletin

23 3.0L TDI Gen 1.2 Emissions Modifications - Repair Authorization

23 18 50 2051969/1 July 25, 2018.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2011 - 2012	All	TDI

Technical Background

Audi of America is requesting your cooperation in supplying us with technical information related to the repair process for vehicles on which the TDI Generation 1.2 Q7 3.0L Emissions Modification is being performed, "Campaign 23V2". Audi will use this information to ensure prompt analysis and resolution of any emerging concerns.

TDI Generation 1.2 Q7 3.0L Emissions Modification has been released for repairs.

Service

If you experience any issues while performing "Campaign 23V2", or after the software update for the TDI Generation 1.2 Q7 3.0L Emissions Modification, follow the process below to open a Technical Assistance Center (TAC) ticket.

Note:

TAC authorization is not required to perform the software update; it is only required if an issue occurs while the update is being performed (for example, if update fails, SVM will not update control modules, etc.) or if an issue occurs after the software update.

If an issue is experienced during or after the software update:

- Create a phone or web contact in the TAC system. Select concern group "Campaign-TDI Emissions Concerns".



- Contact TAC for further instructions. Be sure to record the TAC case number on the repair order.
- After the concern is corrected, findings must be reported before the TAC ticket can be closed.

Note:

Issues related to ODIS should be directed to the ODIS Diagnostic Support Group at 888.896.1298, along with a feedback via the ODIS tool (refer to document AOS-15-03 for ODIS feedback set-up instructions). ODIS issues will still be reviewed as part of the TDI Monitoring Program.



Technical Service Bulletin

Warranty reimbursement for the TDI Generation 1.2 Q7 3.0L Emissions Modification will continue until Audi Warranty communicates an end date to dealers.

Questions or concerns may be directed to Audi Warranty at 866.677.2834 or AudiWarranty@audi.com.

Warranty

Refer to AWA-18-12 and AWA-18-13 for more information.

Additional Information

All parts and service references provided in this TSB (2051969) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.