



Technical Service Bulletin

87 A/C compressor replacement

87 18 88 2035582/3 July 30, 2018. Supersedes Technical Service Bulletin Group 87 number 14-58 dated October 17, 2014 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2009 - 2017	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised header data (Added model year)
2	10/17/2014	Revised header data (Added model years)
1	10/21/2013	Initial publication

The A/C Compressor has been diagnosed as faulty and will be replaced under warranty

Technical Background

When performing replacement of an A/C Compressor under warranty, the amount of refrigerant and oil recovered must be documented.

Production Solution

Not applicable.

Service

Use the Robinair A/C Service Unit to create a printed-out report showing the amount of refrigerant and oil recovered. This report must be submitted with the defective A/C compressor. Follow the steps below:



Technical Service Bulletin

1. Ensure that the A/C service unit shows the correct date and time (Figure 1). If the date and time are incorrect, use the menu to program the correct date and time before proceeding.




Figure 1. Date and time screen.

2. Connect the A/C service unit to the vehicle.
3. Perform a recovery of the system (Figure 2).



Figure 2. System recover in progress.



Technical Service Bulletin

- Record values for **RECOVERED** and **OIL DRAINED** (Figure 3) on the repair order.



Figure 3. Amount of refrigerant recovered (A), and amount of oil drained (B).

- Immediately after recovery, select the **Print** button (Figure 4).



Figure 4. Location of the Print button.



Technical Service Bulletin

6. When the SELECT PRINT TYPE screen opens, use the keypad to select **2) RECOVER CHARGE** (Figure 5).



Figure 5. Selecting a print type.

7. On the next screen, use the keypad enter the last 8 digits of the VIN then press the **START/YES** key (Figure 6).



Figure 6. Enter VIN screen.



Technical Service Bulletin

8. The next screen will request the license plate (Figure 7). Entering the license plate is not necessary. Press the **START/YES** key to continue.



Figure 7. Enter license plate screen.



Technical Service Bulletin

9. The A/C service unit will create a printed report (Figure 8). Send the printed report with the defective A/C compressor. Package the defective compressor in empty packaging from the replacement compressor.



Figure 8. Printed report.



Technical Service Bulletin

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Required Parts and Tools

Tool Number	Tool Description	Quantity
ROB134APF	Robinair A/C Service Unit	01

Additional Information

All parts and service references provided in this TSB (2035582) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.