

[Next Unread Message](#)**View Message**

Sent on	10	10	2018	Expires on	12	31	2018
----------------	----	----	------	-------------------	----	----	------

From	Honda Parts & Service Field Operations
-------------	--

Subject	2006-13 Honda Multi-Model Passenger Front Airbag Inflator Kit Remedy Repairs
----------------	--

On October 10, 2018, American Honda launched an inspection of model year 2006-13 Honda vehicles for concerns related to replacement passenger front airbag inflator kits that were potentially installed incorrectly at Honda dealerships. **Do an iN VIN status inquiry to determine which units in your inventory are affected.**

Basic Concern

Certain dealer technicians did not follow approved installation instructions and may have installed a small number of passenger front airbag inflators incorrectly. In the event of a crash involving airbag deployment, an airbag with an improperly installed inflator may not deploy properly, increasing the risk of injury to occupants of the front passenger seat.

Repair

Per the Service Bulletin, inspect the affected vehicles for correct inflator orientation. Due to potential damage done by an incorrect inflator installation, if one is found, replace the complete airbag module.

Service Bulletin

Service bulletins 18-058,18-059, 18-115 and 18-117, have been posted to the Service Information System (SIS) today, Wednesday, October 10, 2018.They include parts, repair, and warranty information related to this recall.

Parts

Parts to repair vehicles are available via controlled part order as of Wednesday, October 10, 2018.

Warranty

Detailed warranty information can be found in service bulletin 18-058,18-059, 18-115 and 18-117. Please note that the serial number will be required as part of the claim submission. Repairs by airbag module must be accompanied by a photograph. Make sure to enter the serial number correctly and attached the necessary photograph or your claim may be rejected.