

18MY XCL
equipped with
AJ20P

A customer may
complain of a
Check Engine
Lamp illumination
or poor engine
performance

Diagnosis finds DTC P0191-85 stored in the PCM. Thank you to all who supported this investigation with EPQRs and parts returns. Root cause has been identified and an updated PCM calibration is currently scheduled for release in Q4 2018 to resolve this complaint. Do not replace any parts at this time.

SSM 73959 – LR
SSM 73960 -
Jaguar