

Discovery
Sport
RR Evoque
18MY

A Customer may complain of a noise while driving or the complaint may be noted during other workshop repairs.

Inspection of the engine bay finds the heat shield mounted to the turbocharger cracked. This condition may also be noted during other repairs. If this condition is observed, regardless if a complaint exists or repair will be made, please raise an EPQR including pictures showing the heat shield.



Under
Investigation