

RR Velar

A Customer may report that the tail lamp appears to be delaminating or cracking.

The tail lamps may appear to be cracking or delaminating. This may be caused by a manufacturing defect of the lamp assemblies. Should a customer express a concern, please refer to TSB LTB01228NAS1 and replace the affected tail lamp assembly. Please ensure that the replacement lamp assembly has a manufacturing date stamp of 07/07/2018 or later before installing.

LTB01228NAS1
On Sign-off

