

Discovery Sport  
15MY-Onwards

A Customer may report that the tailgate trim panel is coming loose.

TSB LTB00836NAS5 is being updated to change the trim clips being used along with a change to the workshop procedures. Should a customer express a concern, please ensure the latest version of the bulletin is being referenced to perform the repair.

LTB00836NAS6  
On Sign-off