

RR Sport SVR
18MY

Customers may report the finish on the hood is chipping around the vent inserts.

This may be caused by the ribs designed into the back of the plastic vent flange. Revised vents are being produced to address this concern. TSB LTB01211NAS1 is being published to address customer vehicles. UPS N215 is planned for late August release to proactively replace the vents on unsold vehicles and address any paint damage that may have occurred. Should a customer express a concern, please refer to TSB LTB01211NAS1 for repair guidance.

LTB01211NAS1
On Sign-off

