

Subject		Market
Squeak Noise from Front of Vehicle While Driven on Uneven Surfaces - NO.1 Body Mount		USA
Service Category	Section	
Suspension	Front Suspension	
Applicability		
MY 2018 Tacoma MY Tacoma		

APPLICABLE VEHICLES

2018	Tacoma
------	--------

CONDITION

Some 2018 model year vehicles may exhibit a squeak or rattle noise from the Front Right Body Mount Bushing (No. 1) when driving over uneven roads or bumps. Make sure to confirm that noise is coming from Front Right Body Mount Bushing (No. 1) before proceeding.



Location of Front Right Body Mount Bushing (No. 1)

RECOMMENDATIONS

After confirming noise from Front Right Body Mount Bushing (No. 1):

1. **Do Not** disassemble the Front Right Body Mount Bushing (No. 1), please call TAS.
2. Document the Front Right Body Mount Bushing (No. 1) condition by photo for TAS to confirm the phenomenon. (see below for example)



Example of Front Right Body Mount Bushing (No. 1) condition photo

Subject

Squeak Noise from Front of Vehicle While Driven on Uneven Surfaces - NO.1 Body Mount

Market

USA

Applicability

LINK REFERENCES

This Tech Tip does not contain any link references