

## MIL On with DTC P2271?

### AFFECTED VEHICLES

Year	Model	Trim
2007-08	TSX	All

Is the MIL on with DTC P2271 (secondary HO2S [sensor 2] circuit signal stuck rich)? What's likely causing this is the PCM is misinterpreting the A/F sensor (sensor 1) signals, causing the PCM to think that sensor 2 is stuck rich.

To fix this issue, replace both sensors.