

<p>Range Rover RR Sport RR Velar 18MY</p>	<p>Customers may report the charge warning light is illuminated and or the heated seats or steering wheel heater is inoperative.</p>	<p>A customer may express a concern where the charge warning light is illuminated in the Instrument Cluster (IC) or heated seats/steering wheel are inoperative. Through TA reports we have found that poor pin tension and poor pin fit in the LIN connection from the alternator to the Gateway Module (GWM). Please report any cases of this issue through EPQR and provide clear photos of the pins in question.</p>	<p>TBC</p>
---	--	--	------------