

Range Rover
RR Sport
18MY

A Customer may report a 'Suspension fault' message may be displayed on the Instrument Cluster (IC).

This may be caused by a broken suspension air supply unit expansion chamber. If the e-chamber is found to be broken during inspection, in addition to the replacement of the e-chamber a protective foam block will need to be installed.

LTB1180NAS1