

RR Velar	A Customer may report the steering wheel is off center or the vehicle pulls.	The customer may express a concern that the steering wheel is misaligned whilst driving the vehicle in a straight direction. The relationship of the steering wheel to the instrument pack can be perceived to be misaligned due to the interior design of the vehicle. If it is found, the wheel is misaligned more then the example on the SSM submit an EPQR with a picture of the position of the wheel indicating how far off center it is.	SSM 73901
----------	--	--	-----------