

SS: 1033464 - WST 5700XE Sun Visor - LED Skirt Marker Valance Lights water ingress.

WST 5700XE Sun Visor - LED Skirt Marker Valance Lights water ingress

Applicable Vehicles

WST 5700XE

Symptoms

Early failures of LED Marker Valance Lights, Skirt and Sun Visor mounted.

Issue

Current LED Marker Valance Lights installation exposes Lights to water splash and chemical contamination that causes plastic material cracks and water/moisture intrusion resulting in Lights early failures.

Solution


Supplier developed new Marker Valance Light Assemblies with new plastic material more resistant to corrosion and added a seal gasket to provide also a better connector water/moisture sealing.

New parts went into production on March 28, 2018. New parts are available at the PDCs under same part number.


Old Design - Failed Part:



Old Design new:



New improved Design:



Please contact your WST DSM if you have comments or questions.