

SSM73995 - Dynamic Response high pressure pipe fluid leak | TOPIx

Reference	SSM73995
Models	Range Rover / L405
	Range Rover Sport / L494
Title	Dynamic Response high pressure pipe fluid leak
Category	Chassis
Last modified	03-Aug-2018 00:00:00
Symptom	304000 Suspension System
Attachments	Picture 1.JPG
Content	Issue:
	Customer reports red warning lamp illuminated with a message
	"SUSPENSION FAULT"
	"STOP SAFELY"
	"STOP ENGINE"
	Cause:
	Dynamic Response high pressure pipe has a fluid leak due to hose

Action:

material rupture.

Submit an ePQR with the following information

- 1. Provide close up photographs that identify where the leak is coming from, and the whole pipe to show which connection is leaking
- 2. Provide a photograph showing the Test Passed time and date label (not part number label). This is located next to the part number label – see picture attached
- 3. Any other information and observations as to why this leak has occurred
- 4. Replace appropriate part and hold ready for part return request (PRR)

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern. SSM73995 - Dynamic Response high pressure pipe fluid leak | TOPIx

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.