



LTB01228NAS1

TECHNICAL BULLETIN

16 AUG 2018

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

417-01

SUBJECT/CONCERN:

Rear Lamp Cracked And/Or Delaminated

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:
Range Rover Velar (LY)	2018-2019	700125-786268

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:**SITUATION:**

The rear lamp(s) may be cracked and/or appear delaminated.

CAUSE:

This may be caused by a manufacturing defect.

ACTION:

Should a customer express this concern, follow the Workshop Procedure below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY
LR111106	Rear lamp assembly - Right	1
LR111108	Rear lamp assembly - Left	1

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:**NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission system to obtain the latest repair time.

- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Rear lamp assembly - Renew - Single	86.40.70	0.1	01	LR093426
Rear lamp assembly - Renew - Both	86.40.76	0.2	01	LR093427

NOTE:

Normal Warranty procedures apply.

WORKSHOP PROCEDURE:

NOTE:

Renew only a defective rear lamp assembly.

- 1 Remove the affected rear lamp assembly (see TOPIx Workshop Manual section 417-01: Exterior Lighting - Removal and Installation - Rear Lamp Assembly).

CAUTION:

The new rear lamp assembly must have a date stamp of **07/07/2018 or later.**



Inspect and record the date stamp on the **new** rear lamp assembly.

- 3 Install the new rear lamp assembly (see TOPIx Workshop Manual section 417-01: Exterior Lighting - Removal and Installation - Rear Lamp Assembly).