

LTB01149NAS3 TECHNICAL BULLETIN 16 AUG 2018

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

Changes are highlighted in blue

SECTION:

501-14

SUBJECT/CONCERN:

'Hood open' Warning Message Displayed On Instrument Cluster

AFFECTED VEHICLE RANGE:

	MODEL:	MODEL YEAR:	VIN:
--	--------	-------------	------

8/17/2018

LTB01149NAS3 - 'Hood open' Warning Message Displayed On Instrument Cluster | TOPIx

MODEL:	MODEL YEAR:	VIN:
Discovery Sport (LC)	2015 Onwards	501001 Onwards
LR4 (LA)	2014-2016	679426-847658
Discovery (LR)	2017 Onwards	000127 Onwards
Range Rover Evoque (LV)	2012 Onwards	000001 Onwards
Range Rover Velar (LY)	2018 Onwards	700070 Onwards
Range Rover Sport (LW)	2014 Onwards	000001 Onwards
Range Rover (LG)	2013 Onwards	000083 Onwards

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

A 'Hood open' message may be displayed on the Instrument Cluster (IC) or the security system status indicator may give an audible warning to indicate that the hood is not latched correctly. Upon further inspection, the hood is correctly latched.

CAUSE:

This may be caused by water ingress into the hood latch micro switch.

ACTION:

Should a customer express this concern, refer to the Service Information and then follow the Workshop Procedure below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY
LR065340	Hood latch	1

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

\triangle NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission system to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Hood latch - Renew - Discovery Sport (L550)	76.16.21	0.2	28	LR065340
Hood latch - Renew - LR4 (L319)	76.16.21	0.3	28	LR065340
Hood latch - Renew - Discovery (L462)	76.16.21	0.3	28	LR065340
Hood latch - Renew - Range Rover Evoque (L538; 2012- 13MY)	76.16.21	0.3	28	LR065340
Hood latch - Renew - Range Rover Evoque (L538; 2014MY-onwards)	76.16.21	0.2	28	LR065340
Hood latch - Renew - Range Rover Velar (L560)	76.16.21	0.3	28	LR065340
Hood latch - Renew - Range Rover Sport (L494)	76.16.21	0.4	28	LR065340
Hood latch - Renew - Range Rover (L405)	76.16.21	0.3	28	LR065340

△ NOTE:

Normal Warranty procedures apply.

SERVICE INFORMATION:

△ NOTE:

Date shown, **11 10 17** (11 October 2017), for reference only.



The date code (DD MM YY) of the new hood latch must be 27 04 18 (27 April 2018) or later.

WORKSHOP PROCEDURE:

1

Only replace the hood latch that has the microswitch installed.

Renew the hood latch (see TOPIx Workshop Manual section 501-14: Handles, Locks, Latches and Entry Systems - Hood Latch).