

Range Rover
18 MY

A Customer may report the back lighting on the ATCM is dim.

A Customer may report the back lighting on the ATCM All Terrain Switch Pack is dim. After the ATCM software has been updated the back lighting works as intended. If you have corrected this concern with updating the ATCM software please submit an EPQR.

Under
investigation