

Range Rover
18MY

A Customer may report that the second row seat armrest is not operating properly.

Customers may express a concern that the second row deployable seat armrest is stalling when being deployed or stowed. This may be caused by the anti-trap feature being triggered during normal armrest operation. Revised SCMC (Seat Control Module C) software has been developed to address this concern and will be released with PATHFINDER 181 software. Should a customer express a concern, please refer to TSB LTB01229NAS1 and update the SCMC software.

LTB01229NAS1
On Sign-off