

Reference	SSM74025
Models	Range Rover / L405 Range Rover Sport / L494
Title	AJ126 V6 engine - Coolant leak from thermostat housing
Category	Engine
Last modified	30-Aug-2018 00:00:00
Symptom	402000 Cooling System Concerns
Content	<p><u>Issue:</u> The customer reports a coolant leak from the engine compartment which is found to originate from the thermostat housing seam.</p> <p><u>Cause:</u> Multiple process improvements have been implemented at the supplier to mitigate the likelihood of this complaint.</p> <p><u>Action:</u> It is possible the thermostat may suffer consequential damage during a severe overheat event. Investigate and repair any other possible causes of an overheat condition that may exist on the vehicle.</p> <p>Should the VIN reported fall beyond the assured VINs in the applicability table of this document, please raise an EPQR and include pictures of the leak.</p> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>