

Published date: 10/4/2018

Preliminary Information

PIP5337K Shake Or Shudder On Acceleration

Models

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions
			from	to	Engine:	Transmissions:
Cadillac	Escalade	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U
Cadillac	Escalade ESV	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U
Chevrolet	Corvette	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U
Chevrolet	Silverado	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U
GMC	Sierra	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U
GMC	Yukon	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U
GMC	Yukon XL	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U

Please refer to bulletin 16-NA-175 for vehicles equipped with the 8L90 automatic transmission RPO (M5U) with shudder concerns.

Please follow this diagnostic or repair process in Bulletin 16-NA-175, thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed."













GENERAL MOTORS

© 2018 General Motors. All Rights Reserved.