



Preliminary Information

PIT5298C Installation of Upfitter Auxiliary Switches (RPO 9L7)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500	2014	All	All	All	All
Chevrolet	Silverado	2015 - 2018	All	All	All	All
Chevrolet	Silverado 2500/3500	2019	All	All	All	All
GMC	Sierra 1500	2014	All	All	All	All
GMC	Sierra	2015 - 2018	All	All	All	All
GMC	Sierra 2500/3500	2019	All	All	All	All

Supersession Statement

This PI was superseded to update model years. Please discard PIT5298B.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

A Dealer or Upfitter may be looking for information on installing RPO 9L7 Upfitter Auxiliary Switches.

The Upfitter Auxiliary Switches are located under the climate controls in the center of the dash.

Recommendations / Instructions

Reference the latest version of GM Upfitter Integration Bulletin 110. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

Additional SI Keywords

accessories accessory accy aux electrical fuse gmupfitter switch UBEC underhood

