



Preliminary Information

PIP5600 DTC P0011 Setting

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (new Model)	2019	All	All	5.3L 6.2L, L84, L87	All
GMC	Sierra 1500 (new Model)	2019	All	All	5.3L 6.2L, L84, L87	All

Involved Region or Country	North America
Condition	A vehicle may come in with a DTC P0011 set
Cause	A sticking oil control solenoid for the cam actuator

Correction:

Since the L84/L87 is on exchange, (PIP5567) engineering has decided that we will authorize the replacement of the OCV valve bolt for P0011 DTC's

Replace the OCV and place it in a bag to be shipped back to engineering.

This Pi will be changed to a bulleting or deleted when the engine exchange ends.

Warranty Information

Labor Operation	Description	Labor Time
4064250	Camshaft Position Actuator Solenoid Valve Replacement	Use published Time

Version History

Version	1
Modified	10/12/2018 - Created om



GENERAL MOTORS