

2018-10-19

Purpose for Service Bulletin

Refer to [Figure 1](#) and [Table 2](#). There were a number of kits produced with defective support tubes (8). These tubes only had holes on one side but should have holes on both sides. The support tubes are now warrantable items and the entire kit does not need to be returned.

All vehicles with Tour-Paks.

Markets Affected

Refer to Table 1.

Current Part No.	Item Description	New Part No.
N/A	Support tube	53809-02

If dealer finds a H-D Detachables Touring Tour-Pak Rack kit (Part No. 53276-04A) with a defective support tube, warranty the support tube only. Entire kits are not warrantable for this condition.



NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

[illegible]

Table 2. Service Parts Table

Item	Description (Quantity)	Part Number
1	Rack, detachable tour-pak	Not Sold Separately
2	Nut, cap, hex lock, 1/4-20 (5)	7887
3	Washer (10)	6703
4	Spacer, rack (5)	53799-99
5	Screw, cap, hex head 1-3/4 inch (5)	Not Sold Separately
6	Screw, cap, hex head 2-1/4 inch (5)	2821
7	Plug, universal flat head (2)	Not Sold Separately
8	Tube, support, top	53809-02
9	Latch assembly (2)	50300108
10	Stud, splined (2)	Not Sold Separately