



GROUP
Electrical

MODEL
**2017MY
Sorento (UMa)**

NUMBER
PS582 (Rev 1, 10/17/2018)

DATE
October 2018



TECHNICAL OPERATIONS

SUBJECT:


**BODY CONTROL MODULE (BCM)
PART NUMBER CHANGE**

* NOTICE

This bulletin has been revised to include additional information. New/revised sections of this bulletin are indicated by a black bar in the margin area.

This Pitstop provides information regarding a change made to the software logic of the service part replacement Body Control Module (BCM) for the 2017MY Sorento (UMa). If the BCM is replaced with a normal service part, the horn answerback feature may not be available for selection within the settings menu of the instrument cluster. If the customer prefers the vehicle retains this feature, install the appropriate part below.

Normal Service Part	Service Part w/ Answer Back Feature
95410 C6020	95410 C6020AS
95410 C6040	95410 C6040AS



Body Control Module (BCM)