

Reference	SSM73955
Models	Range Rover Velar / L560
Title	Range Rover Velar with Dynamic Front Bumpers, Front PDC False activation
Category	Body
Last modified	10-Jul-2018 00:00:00
Symptom	108000 Ext. Trim/Accessories
Attachments	Standard vs Dynamic Bumpers .pdf

Content

Issue:

Range Rover Velar Customers may report that the Front Park Distance Control (PDC) Sensors are activated although no obstacle is evident. **Please note;** this concern only occurs on vehicles fitted with Dynamic Bumpers, please see attachment for example

Cause:

Incorrect detections due to PDC Sensors picking up the Exterior Styling fins on the Dynamic Bumper

Action:

No repair or Diagnosis is available at this time, Land Rover Engineering are aware of the concern and are working on a fix, A TSB or SSM will be issued once the fix is available

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.