

<b>Reference</b>	SSM73961
<b>Models</b>	Range Rover Evoque / L538
<b>Title</b>	Range Rover Evoque Telematics Antenna Replacement
<b>Category</b>	Electrical
<b>Last modified</b>	13-Jul-2018 00:00:00
<b>Symptom</b>	207000 Entertainment Systems
<b>Attachments</b>	L538 Assured Spoiler ID methods1.pdf

**Content**      **Model:** Range Rover Evoque 15-16MY

**Issue:** Telematics Antenna Replacement - Check Date Code Prior to Installation.

**Cause:** Assured part to address connection issue internally in the rear spoiler assembly to the telematics antenna.

**Action:** In the event the telematics antenna requires replacement, inspect the new antenna prior to installation. The new antenna must have a white paint dot on the cable and a date code of 22-04-2016 (22 April 2016) or later. See attachment.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.