

<p><b>Range Rover RR Sport</b></p>	<p><b>A Customer may report the steering feels heavier than expected.</b></p>	<p><b>A customer may report the vehicle steering feels heavy and no warnings will be visible on the Instrument Cluster. This may be caused by the Bulkhead Seal Assembly binding with the steering column upper shaft. If the Bulkhead Seal is found to be binding, please get a video and attach it to an EPQR. Replace the Bulkhead Seal and upper steering column shaft and hold the parts for PRR.</b></p>	<p><b>SSM 73943</b></p>
--	---	--	-----------------------------