

SSM  
47614

Some 2011 - 2014 Mustang vehicles equipped with a 3.7L V6 engine and MT82 manual transmission may exhibit a vibration felt in the shifter, and/or the seat track and steering wheel, on deceleration between 3500 and 2000 engine RPM. This an operating characteristic of the vehicle and no repairs should be attempted.