



# Parts Bulletin

TITLE:

**Service Campaign S29846: Coolant Expansion Tank Bleeder Hose  
Model Year 2016 XC90**

<b>GROUP:</b> 26	<b>CAT/NO:</b> S29846	<b>REFERENCE BULLETINS:</b> QB S29846	<b>CAR MARKET:</b> United States and Canada	
<b>COPY TO / CIRCULATIONS (PLEASE INITIAL):</b>			<b>ISSUE DATE:</b> 2018-05-02	<b>STATUS DATE:</b> 2018-05-02
<b>GENERAL MANAGER</b>	<b>PARTS MANAGER</b>	<b>SERVICE MANAGER</b>	<b>SALES MANAGER</b>	
				<b>Page 1 of 1</b>

**“Right first time in Time”**

**Reference Bulletins: QB S29846**

Volvo Car USA LLC and Volvo Car Canada LTD (Volvo) on behalf of Volvo Car Corporation, has decided to launch Service Campaign S29846 on certain model year 2016 XC90 vehicles.

Volvo has identified that engine coolant may leak due to an insufficient quick connector in the coolant expansion tank bleeder hose. Should this condition occur, a message in the Driver Information Module (DIM) will appear informing the driver about low coolant level and in a worse case situation high engine temperature.

The corrective action is to replace the coolant expansion tank bleeder hose.

Service Campaign S29846 affects 35,037 vehicles in the U.S. and 2,832 in Canada.

The following part number applies:

<b>Part Number</b>	<b>Description</b>	<b>Qty</b>
32252211	Bleeder hose	1