



# Technical Journal

TITLE:

**P6-XC40 Front license plate screws**

<b>REF NO:</b> TJ 33771.1.1	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States	
<b>PARTNER:</b> 3 US 7510 Volvo Car USA		<b>ISSUE DATE:</b> 2018-04-30	<b>STATUS DATE:</b> 2018-05-04
<b>FUNC GROUP:</b> 8611	<b>FUNC DESC:</b> Bumper, front	Page 1 of 2	

“Right first time in Time”

## Attachment

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536							2019-9999		0000329-9999999	201746-999952

## CSC Customer Symptom Codes

Code	Description
ZW	Exterior/Component exterior wrong installation/missing

## VST Operation Number

## DTC Diagnostic Trouble Codes

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

## Text

### DESCRIPTION:

XC40 License plate screws

**SERVICE:**

Install front license plate using four (4) Wurth screws P/N 02151012. (For claiming use P/N 2151012)

Canadian market use Wurth screw P/N 140.70604 (For claiming use P/N 2151012)

**VEHICLE REPORT:**

When submitting a Vehicle Report for a condition described in this TJ, use concern area "Vehicle Report" and sub concern area "Support Not Needed" with function group 8611.