

SERVICE BULLETIN 556: REPLACE HEADSTOCK TIDY



Notice Information

Ref	8560
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CAN) – October 22, 2018

TOL Ref. # 8560-SVC

Service Bulletin 556: Replace Headstock Tidy

Triumph has released **Service Bulletin 556**. The headstock tidy on certain Street Scrambler, Street Twin and Street Cup models has been refined to allow the main harness and clutch cable to locate in a more natural position during operation.

Dealers are requested to replace the headstock tidy and it's fixings as described in the attached [Service Bulletin 556 PDF](#). Motorcycles in the affected VIN ranges listed in the chart below must be modified prior to delivery to the customer, or at the next visit to the dealership.

SERVICE BULLETIN 556: Headstock Tidy Replace		
Bulletin Number	Models Affected	VIN Range
556	Street Scrambler	From 798290 to 910740
	Street Twin	From 731919 to 913928
	Street Cup	From 780697 to 896532

Note: Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory. The modified motorcycles can be identified by checking the 'Outstanding Service Bulletins' on Warranty Online.

Consult **Triumph Online (TOL) / Service Bulletin Page** (Bulletin # 556) or the attached [Service Bulletin 556 PDF](#) for complete instructions. Please ensure that all relevant staff are up to date on these service instructions.

Reminder: Use the “**VIN Enquiry**” function within TOL (found under the **Service / Technical** drop down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives or a Triumph owner visits your dealership. For more information, please contact Triumph Customer Support at (888) 284-6288.