



# SERVICE BULLETIN

Classification:

EL18-032

Reference:

NTB18-073

Date:

October 30, 2018

## 2018 TITAN; IPDM E/R SERVICE INFORMATION

**APPLIED VEHICLES:** 2018 Titan (A61)

### SERVICE INFORMATION

When diagnosing an electrical issue that involves the IPDM E/R, make sure to:

- Check for blown fuses in the IPDM E/R.
- Replace any blown fuses and recheck the issue.

**NOTE:**

- Do not replace an IPDM E/R if replacement of a fuse will resolve the issue.
- Part numbers for IPDM E/R fuses are listed in the Parts Information on the next page.

IPDM E/R Example




Figure 1

### CLAIMS INFORMATION

If the IPDM E/R is replaced, do not remove the fuses or any other components. **The old part must be returned complete.**

An IPDM E/R that is returned with missing or physically damaged components will be charged back to the dealer.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

## PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
5 Amp Fuse	24319 – 8990A	As needed
10 Amp Fuse	24319 – 89910	
15 Amp Fuse	24319 – 89915	
20 Amp Fuse	24319 – 89920	
30 Amp Fuse	Not available from Nissan PDC as of the date of publication of this bulletin	N/A

## AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
October 30, 2018	NTB18-073	Original bulletin published