



Bulletin No.: PIT5638
Published date: 10/29/2018

Preliminary Information

PIT5638 Service Brake Assist Message with DTC a C053D or C058E

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	All
GMC	Sierra 1500 (New Model)	2019	All	All	All	All

Involved Region or Country	North America
Condition	In some rare situations, a customer may comment on a "Service Brake Assist" message and they may have a hard brake pedal or increased effort is needed to depress the brake pedal, which may extend stopping distances. When checking for DTC's, a current or history C053D and/or C058E will be set in the K160 Brake System Control Module (formerly known as the EBCM).
Cause	Under investigation

Correction:

If no issues are found after performing normal SI diagnostics and the DTC clears, then perform a road test. If the condition does not return, no repairs should be made at this time. GM Engineering is working to expedite a software update for the Brake System Control Module to address this condition.

NOTE: When a fix is available, this PI will be converted into a service bulletin.

Version History

Version	1
Modified	10/29/2018 - Created on

