

Technical Service Bulletin

93 Battery light on, DTC P0AA600 and/or P0E7400 stored in the battery regulation control module - Repair Authorization

93 18 10 2052382/1 September 14, 2018.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3 e-tron	2017 - 2018	All	e-tron

Condition

Customer states:

· Battery light is illuminated.

Workshop findings:

One or more of the following DTCs may be stored in the battery regulation control module, J840 (address word 008C):

DTC P0AA600 (Hybrid/EV Battery Voltage System Isolation Fault).

And/or

DTC P0E7400 (Hybrid/EV Battery Voltage Internal Isolation Fault).

Technical Background

In an effort to gain information on the DTC codes for the vehicles listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition:

- 1. Verify the condition.
- 2. Park vehicle under EV quarantine conditions: (Electrical System >> High-Voltage Vehicle General Information >> 00 General, Technical data >> Lithium-Ion High-Voltage Battery >> Procedure for Faulty or Accident-Damaged High-Voltage Vehicles).



Technical Service Bulletin

3. Please attach the DTC and diagnostic log to the TAC ticket, and call TAC.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2052382) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.