



Service Information

Special Tools & Equipment

Number: ATE-18-15

Subject: John Bean VAS701001 Aligners Pro42 Program Update
version 5.8 (08.2018) and Pro42 Vehicle Data Update (VAG-
08.2018)

Date: Sep. 7, 2018

Supersedes ATE-18-07 dated April 20, 2018 due to Vehicle Data software updates and supersedes ATE-17-21 dated December 8, 2018 due to Software Program Update.

This communication provides important information on how to obtain and install the latest software for the **John Bean VAS701001 alignment machine model.**

Latest Software Versions Released:

- John Bean Pro42 Software Update VAG Version 5.8 August 2018 (48,274 KB)
- John Bean Pro42 Vehicle Database Update August 2018 (274,136 KB)

Installation Requirements:

- All John Bean VAS701001 Aligners must be previously updated to **Pro42** Program software version 5.0 or higher before performing this update.
- Attain a copy of Vehicle Specification updates installation instructions (see attachments)
- Dealers must download **John Bean pro42_software_update_vag_version_58.exe** file from ServiceNet>>Workshop Equipment>> Wheel Alignment Software >> John Bean>>Alignment Software Updates (PRO42)
- Dealers must download **John Bean pro42_data_base_vag082018.exe** file from ServiceNet>>Workshop Equipment>> Wheel Alignment Software >> John Bean>>Alignment Software Updates (PRO42)

Installation:

To update the John Bean the VAS701001 aligner, please read and follow the Vehicle Specification updates installation instructions attached.

Questions regarding installation of software updates to VAS701001 (after they have been downloaded), can call EquiServ technical support desk (service group for John Bean) at 800-225-5786. EquiServ will Also be able to help with Aligner software and specifications installed from CD.



Software PRO42 version 5.8, Aout 2018

(pour VAS 701 001)

Suppléments/Changements par rapport à la version 5.7

Software PRO42 Version 5.8, August 2018

(for wheel aligner VAS 701 001)

Supplements/Changes compared to Version 5.7

Volkswagen	Tiguan [BW2]	2
	Crafter [SY,SZ]	2
Audi	Q8 [4MN]	2
Skoda	-	-
Seat	-	-
Bentley	-	-
Lamborghini	-	-
Porsche	-	-
		1 = Nouveau / New 2 = Changement / Change

Specs Update News

Snap-on Equipment

**Base de données de Véhicule pour software Pro42 (pour modèles VAS 701 001)
Pro42 DB VAG-082018*, Aout 2018**
Suppléments/Changements par rapport à la version de VAG - 052018

**Vehicle Data Base for Software Pro42 (for wheel aligner VAS 701 001) Pro42
DB VAG-082108*, August 2018**
Supplements/Changes compared to Version VAG – 052018

Volkswagen	Atlas [CA]	2
	T-Roc [A11]	2
	Crafter [SY,SZ]	2
<i>L'Amérique du Nord, North America</i>	Atlas [CA1] (G02) Nordamerika	2
<i>Mexique/Mexico</i>	Teramont NAR [CA1] (G02) MEX	1
<i>Russie, GCC,/Russia, GCC</i>	Teramont NAR [CA1] (G01) RUS, GCC	1
<i>Chine/China</i>	Teramont CS [0A1] (G01) China	1
<i>Brésil/Brasil</i>	Verschiedene Modelle, various models	2
Audi	A1 2019 [GB]	1
	Q3 2019 [F3]	1
	A6 2019 [4A0]	2
	A8 [4H]	2
	Q7 [4MB]	2
Skoda	Rapid NH [G80] Russia	2
Seat	-	-
Porsche	911 [997]	2
	911 [991]	2
Bentley	-	-
		1 = Nouveau / New 2 = Changement / Change *= les deux premiers chiffres indiquent le mois, les quatre derniers chiffres du numéro de l'année



Installation Instructions

Release Date:
October, 2015

Model(s)
Affected:

TEEWA553V

T3-76126BV1 Rev C

VAG Pro42 instructions for software installation

ACTION TO BE TAKEN:

1. This software is only for VAS 701 001 Aligner. To determine if the aligner requires this update click on the “About” icon from the Home Screen. If the current version is 5.2 there is no need to proceed. If the current version is 5.0 or greater from the portal download version 5.2 to a flash drive.



2. Shut down the alignment software by clicking the “X” in the upper right hand corner of the Home Screen.
3. Insert the flash drive into one of the empty USB ports on the alignment system.
4. If Autoplay is not turned on Navigate to the flash drive by holding down the Windows key and the letter “E”. If autoplay is active click “Open folder to view files” from the popup.




+ E




5. Double click the “VAS 701 001 ver. 5.2.exe” file to begin the installation.


NOTE: DO NOT POWER DOWN THE ALIGNER AT ANY TIME DURING SOFTWARE INSTALLATION.




6. If attempts are made to install this software on a non VAS 701 001 system the installer will receive a popup message informing them that this software is “Only for Pro42 VAS 701 001 update!”




7. The file extract before the installation process.




8. The system will prepare for software Installation. An overall software installation progress bar will appear.




9. A VAGPortal InstallShield Wizard shows the progress of the installation.




10. The user will be prompted about a "Driver" during the install. This "Driver" must be installed. Click "Install this driver software anyway".



11. The user will be prompted to attach a device to the computer, this device is the camera(s) already attached. Click on "OK" to continue.



- Click on "Finish" to complete the successful install.



- From the Home screen click on the about icon to confirm the updated version.

