

Measure no.

US 64444456-02

Subject

Loss of F1-Push To Talk

Status date (mm/dd/yy)

10/11/18

Status

Created

Organization

US, MOT

Date created (mm/dd/yy)

10/11/18

Created by

Brenton Myers

PQM Problem reference**Release date (mm/dd/yy)****Approved by**

Vehicles affected**E series**

K52

Engine**Body****Production period (from/to)**

(mm/dd/yy)

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

/

Complaint

After updating the Authority vehicle I-Level to K001-18-07-520 the F1-Push To Talk (PTT) function is deactivated.

CauseProgramming to I-Level K001-18-07-520

Measure

Changes from last version:

-02 = The specific ISTA software Level was removed.

Measure:

No Programming is to be done to the bikes until further notice.

If a programming is necessary e.g. a control unit replacement. Create a PuMA case.

BMW Motorrad Development department is aware of this situation and is currently working on a solution.

Complaint

Fault location	Fault type	Fault place	Fault conditions
Flashing	Failure	Both sides / all	Permanent

Cause

#	Fault location	Fault type	Fault place
1	63/13 Front turn indicators		
Repair Task		Special Clearance	Area
		No	Electrics/Electronics

Fault codeUSA019

Progman / DIS / ISTA / ISTA/P

System	State	Version
---------------	--------------	----------------

© 2002-2018 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.