

[Next Unread Message](#)[View Message](#)

Sent on	11	09	2018	Expires on	11	28	2018
From	Motorcycle National Field Service						
Subject	2018 GL1800 Navi Software Update, CB Radio Performance - Fixed						

November 9, 2018

2018 GL1800 Navi Software Update, CB Radio Performance - Fixed

On October 25, American Honda informed dealers that the Navigation software *Update 1* (published Oct. 4th) for the 2018 Gold Wing interfered with the performance of the Genuine Accessory CB radio, greatly diminishing its volume output.

Honda has resolved the software problem and a revised Navigation software *Update 1* is currently available on the Honda Powersports website. Dealers and Customers can now download the software from the website and upload it to the 2018 Goldwing using the instructions included on the site.

<https://powersports.honda.com/goldwingupdate.aspx>

If you have any questions, please contact AHM TechLine through TechLine Connect on *iN* or contact your District Service Manager.

Sincerely,
American Honda Motor Co., Inc.
Motorcycle Division

Bulletin # 18-0350