

SSM
47509

Some 2019 Flex vehicles equipped with SYNC 3 without navigation may exhibit a compass that is stuck and/or does not indicate the correct direction. Do not attempt any repairs at this time. Engineering is investigating, monitor OASIS for updates.