

SSM
47540

Some 2018 F-150, Expedition, and Navigator vehicles may exhibit a concern of inoperative adaptive cruise control with no associated DTCs. This concern may occur if hot in run or start switched power is not present at the anti-lock brake system (ABS) module on circuit CBB17. A load test is recommended to test the ABS module power and ground circuits.