

BR 190 - Worn seat cover in area of side bolster (code 555)

Topic number	LI91.18-P-067198
Version	2
Function group	91.18 Seat covers
Date	10-08-2018
Validity	MODEL 190.3## (code 555) up to production date 12/2016
Reason for change	Damage code adjusted (fault type 22 "Chafes")
Reason for block	

Complaint:

Worn seat cover in area of side bolster.

Attachments	
File	Description
Beschädigung_Abnutzung Sitzbezug.JPG	Damage/wear on seat side bolster/seam

Cause:

Material wear in area of seat cushion and/or backrest.

Remedy:

Replace left and/or right front seat backrest cover.

Important: The trim in the seat backrest must not be removed. The cover can be unhooked (see instructions for unhooking cover from trim).

In the event of complaints after a cleanpoint of 12/2016 vehicle production, please create a PTSS case.

Attachments	
File	Description
Bezug aushängen an Blende.pdf	Instructions for unhooking cover from trim

Symptoms

Body / Seat / Seat cover / Chafed through

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 190 910 25 01			Backrest cover		Footnote (ES2) as per EPC	X

XENTRY TIPS

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			91A15 22	Left front seat backrest cover
			91N15 22	Right front seat backrest cover

Attachments

Beschädigung_Abnutzung Sitzbezug.JPG:









