



## Technical Tip

<b>Topic</b>	27-18-06TT - Adaptive Cruise Control DTC C110300 Resulting from Grille Removal
<b>Market area</b>	United States 444 Volkswagen of America, Inc. (6444)
<b>Brand</b>	Volkswagen
<b>Date</b>	August 17, 2018

## Condition

**ATTENTION:****THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.****TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

### Adaptive Cruise Control DTC C110300 Resulting from Grille Removal

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas	2018	All	All	All	All

## Technical Background

Front Assist/Adaptive Cruise Control misalignment can be caused by front grille replacement or adjustment.

Be aware: 0013 - Distance Control (ACC) fault code “C110300: Adaptive cruise control sensor misadjusted” can be set when the front grille is moved. The C110300 fault code will not be set until the vehicle has been driven for several minutes after the grille movement.

## Service

When the front grille is disturbed or replaced, the Adaptive Cruise Control (ACC) Calibrating process is required as a consequential repair.

## Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2052209/1	8/17/18	Original publication.

© 2018 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.