Technical Tip

Торіс	27-18-07TT - Replacing the Adaptive Cruise Control (ACC) Module -J428-	
Market area	United States 444 Volkswagen of America, Inc. (6444)	
Brand	Volkswagen	
Date	August 24, 2018	

Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN. TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Replacing the Adaptive Cruise Control (ACC) Module -J428-

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Passat, Golf, Golf R, Golf Sportwagon	2015-2018	All	All	All	AII
Atlas, Tiguan LWB	2018	All	All	All	All
Jetta (BU)	2019	All	All	All	All

Technical Background

If the ACC Module -*J428*- will not calibrate after replacement, there may be various data faults in the driver assistance systems.

Service

When replacing the -*J428*-, the test plan "Commissioning" needs to be completed before the calibration can be completed.

After running Guided Fault Finding diagnosis and the replacement test plan, with control module software configuration having been completed:

- Right click on diagnostic address 13, Distance Regulation -J428-.
- Select Guided functions.
- Select "Commissioning" and complete the test plan.

Additional Information

Revision History						
Revision Number	Released Date	Reason For Update				
2052265/1	4/24/18	Original publication.				

© 2018 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.