



Technical Tip

Topic	96-18-02TT – Drive Mode Rotary Switch Design Change - E881 -
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	October 12, 2018

Condition

ATTENTION:
THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Rotary Switch Design Change

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas	2019	All	All	All	All

Technical Background

Rotary switch running design change.

Service

The drive mode rotary switch with chrome ring and without chrome ring both are acceptable. Spare parts may come with or without chrome ring.





Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2052667/1	10/12/18	Original publication.

© 2018 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.