
2019 RDX Timing Chain Case Cover Oil Leak

Background

American Honda Motor Co., Inc. (AHM) is investigating certain 2019 RDXs with a client complaint of leak from the timing chain case cover. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. Vehicle must be within the VIN range below:
5J8TC1...000052 to 5J8TC1...000292
2. Must confirm leak from the tensioner cover.
3. No attempt has been made to repair this issue.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.