

GPOP - Issue Review System

Part Number: 68295438A\$

Part Description: Turbocharger

Issue Description: There is an exhaust brake switch improvement on the latest Powertrain Control Module (PCM) flash update detailed in a Service Bulletin under Vehicle Performance. This new PCM software fixes an issue where the exhaust brake mode would default to an "on setting" in the PCM but not update the EVIC and therefore the exhaust brake switch would not indicate the correct exhaust brake mode status on the dash. Do not replace the turbocharger for complaints of exhaust brake operating when the switch is off. Replacing the turbocharger will not address these complaints. Update the PCM with the new software version to correct this issue.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
